

XL44 POUCH LAMINATOR 110V WIRING DIAGRAM

LEGEND

- A INDICATOR LIGHT
- B HEAT CONTROL
- C TERMINAL BLOCK
- D SLIP RING
- E POWER RELAY
- F MAIN POWER RECEPTACLE
- G MUFFIN FAN
- H PRM202 SHADED POLE MOTOR
- J MAIN POWER SWITCH
- K FUSE HOLDER & 1/2 AMP FUSE
- L 47K 1/4W RESISTOR

